

systems and procedures
for

maintaining and utilizing
Common Facilities



Kallamathu Govindar Murugan College, Pollachi
Water Doctor Maintenance Register

Location: (M.R.D.) ?

Date	Last Cleaning On	Cleaned By	Signature	Next Cleaning On
20-12-19	20-12-19	A. Ramasami	H. Srinivas	20-12-19

Crossfit
WATER PURIFYING PVT. LTD.


Model No. _____
Serial No. _____
Date of Purchase _____
Warranty Period _____
1st Year _____
2nd Year _____
3rd Year _____



Nallamuthu Gounder Mahalingam College, Pollachi
Water Tanks Maintenance Register

Location : *Library Tank.*

Date	Last Cleaned On	Cleaned By	Signature	Next Cleaning On
<i>10.1.19.</i>	<i>10.1.19.</i>	<i>A. Nandhan</i>	<i>A. Nandhan</i>	<i>14.3.19.</i>




Nallamuthu Gounder Mahalingam College, Pollachi
Water Tanks Maintenance Register

Location: *Main Tank.*

Date	Last Cleaned On	Cleaned By	Signature	Next Cleaning On
<i>10.1.19</i>	<i>10.1.19</i>	<i>A. Enigma</i>	<i>A. Enigma</i>	<i>14.3.19</i>



The image shows the front cover of a book. The cover has a vibrant red background with a dense, white, marbled or 'stone' pattern. A central, rectangular, off-white paper label is pasted onto the cover. The label contains the title and date in a simple, black, sans-serif font. The book is resting on a light-colored wooden surface, and the spine of the book is visible on the left side.

January 2018
Infrastructure Grievances &
Redressal